





Inserts

ribbed - rectangular



Other Mechanical Parts



P1987

OTHER MECHANICAL PARTS

Material

Low density polyethylene, black.

Important Notes

Sold subject to minimum pack quantity.

Technical Notes

Insert ribs provide secure fitting.

Order No.	External cap dim.	Tube wall thickness	h
P1987.020-10-0	20x10	1,0-2,0	11,0
P1987.020-15-0	20x15	1,0-2,0	11,5
P1987.025-10-0	25x10	1,0-1,5	11,5
P1987.025-15-0	25x15	1,0-2,5	11,5
P1987.025-20-0	25x20	1,0-3,0	11,5
P1987.030-10-0	30x10	1,0-1,5	11,5
P1987.030-15-0	30x15	1,0-2,5	11,5
P1987.030-20-0	30x20	1,5-3,0	11,5
P1987.030-25-0	30x25	1,5	13,0
P1987.035-10-0	35x10	1,0-2,0	11,5
P1987.035-20-1	35x20	1,0-2,5	11,5
P1987.035-25-0	35x25	1,0-3,0	11,5
P1987.040-10-0	40x10	1,5	10,5
P1987.040-15-0	40x15	1,0-1,5	12,0
P1987.040-20-0	40x20	1,0-2,0	12,0
P1987.040-25-0	40x25	1,0-3,0	11,5
P1987.040-30-0	40x30	1,0-3,0	12,0
P1987.040-35-0	40x35	1,0-3,0	12,0
P1987.045-15-0	45x15	1,5-2,0	11,0
P1987.045-20-0	45x20	1,5-2,0	11,5
P1987.045-25-0	45x25	1,5-2,0	14,0
P1987.045-30-0	45x30	1,0-2,5	12,0
P1987.045-35-0	45x35	1,0-3,5	12,0
P1987.050-10-0	50x10	1,0-1,5	12,0
P1987.050-20-0	50x20	1,0-3,0	14,0
P1987.050-25-0	50x25	1,5-2,5	14,5
P1987.050-30-0	50x30	1,5-2,0	13,5
P1987.050-35-0	50x35	1,0-3,5	14,5
P1987.050-40-0	50x40	1,5-2,5	12,5
P1987.055-34-0	55x34	1,5	14,0
P1987.055-40-0	55x40	1,5-4,0	14,5
P1987.060-15-0	60x15	1,0-2,0	14,5
P1987.060-20-0	60x20	1,0-3,0	14,5
P1987.060-25-0	60x25	1,0-2,5	14,0

Inserts

ribbed - rectangular



Order No.	External cap dim.	Tube wall thickness	h
P1987.060-30-0	60x30	1,5-2,0	15,0
P1987.060-35-0	60x35	1,5-3,5	15,0
P1987.060-40-0	60x40	1,0-3,0	14,0
P1987.060-50-0	60x50	1,5-3,5	14,5
P1987.070-20-0	70x20	1,0-2,0	17,0
P1987.070-25-0	70x25	1,5-2,0	17,0
P1987.070-30-0	70x30	1,5-2,0	18,0
P1987.070-40-0	70x40	1,5-2,0	18,0
P1987.080-20-0	80x20	1,5-2,0	18,0
P1987.080-30-0	80x30	1,0-2,5	14,5
P1987.080-40-0	80x40	1,0-3,0	14,5
P1987.080-50-0	80x50	2,0-4,0	24,0
P1987.080-60-0	80x60	2,5-3,0	24,0
P1987.100-40-0	100x40	2,0-4,0	14,5
P1987.100-50-0	100x50	2,0-3,0	24,0
P1987.100-50-1	100x50	3,2-5,0	24,0
P1987.120-30-0	120x30	1,5-2,0	14,5
P1987.120-40-0	120x40	2,0	-
P1987.120-60-0	120x60	2,0-4,0	24,5
P1987.120-80-0	120x80	2,0-3,0	24,0
P1987.140-80-0	140x80	2,0-4,5	20,0
P1987.150-100-0	150x100	3,0-8,0	27,0